

# 000459: Bender et al. Replacement Sheet 1/12






FIG. 1 PRIOR ART

## 000459: Bender et al. Replacement Sheet 2/12





PRIOR ART

# 000459: Bender et al. Replacement Sheet 3/ 12





FIG. 4 PRIOR ART

### 000459: Bender et al. Replacement Sheet 4/12

#### FAILURE TRANSITIONS ARE NOT SHOWN



#### FAILURE TRANSITIONS ARE NOT SHOWN





FIG. 5 PRIOR ART

### 000459: Bender et al. Replacement Sheet 5/ 12








FIG. 6 PRIOR ART

000459: Bender et al. Replacement Sheet 6/ 12



# 000459: Bender et al. Replacement Sheet 7/ 12






FIG. 8 PRIOR ART

## 000459: Bender et al. Sheet 8/ 12




FIG. 9





FIG. 10






FIG. 12

000459: Bender et al. Sheet 12/12




FIG. 13